PRESERVATION OF THE HIGH QUALITY FACTOR AND ACCELERATING GRADIENT OF Nb₃Sn-COATED CAVITY DURING PAIR ASSEMBLY

G. Eremeev^{1,*}, U. Pudasaini², S. Cheban¹, J. Fischer², D. Forehand², S. Posen¹, A. Reilly², R. Rimmer², B. Tennis¹ ¹Fermi National Accelerator Laboratory, Batavia, IL, USA ²Thomas Jefferson National Accelerator Facility, Newport News, VA, USA

Abstract

Two CEBAF 5-cell accelerator cavities have been coated with Nb₃Sn film using the vapor diffusion technique. One cavity was coated in the Jefferson Lab Nb₃Sn cavity coating system, and the other in the Fermilab Nb₃Sn coating system. Both cavities were measured at 4 K and 2 K in the vertical dewar test in each lab and then assembled into a cavity pair at Jefferson Lab. Previous attempts to assemble Nb₃Sn cavities into a cavity pair degraded the superconducting properties of Nb₃Sn-coated cavities. This contribution discusses the efforts to identify and mitigate the pair assembly challenges and will present the results of the vertical tests before and after pair assembly. Notably, one of the cavities reached the highest gradient above 80 mT in the vertical test after the pair assembly.

INTRODUCTION

As the part of the development of Nb₃Sn for SRF applications in 2018, two Nb₃Sn-coated CEBAF cavities were assembled into a cavity pair, the standard step during CEBAF cryomodule assembly process. As a part of the pair qualification process, both Nb₃Sn-coated cavities assembled into the cavity pair were measured in the vertical dewar and were found to degrade significantly from their pre-pair assembly qualification tests, Fig. 1. The pair was taken apart and each cavity was measured in the vertical dewar separately. These tests confirmed that superconducting RF properties of both Nb₃Sn-coated cavities degraded [1].

Subsequent studies revealed that Nb₃Sn-coated SRF cavities are unexpectedly very sensitive to mechanical tuning at room temperature, which is a part of the standard process to qualify an SRF cavity for cryomodule integration. In the vertical dewar tests of Nb₃Sn-coated cavities the low-field surface resistance was observed to increase by about 100 nΩ and exhibit strong field dependence after room temperature mechanical tuning of a few hundred kilohertz. It must be noted that, in a different study by Posen et al., it was found that mechanical tuning done at cryogenic temperatures does not impact coated cavity performance significantly [2].

In order to mitigate the performance degradation after the room temperature tuning, the mechanical tuning step was eliminated from the next Nb₃Sn-coated cavity pair assembly. In addition to eliminating room temperature tuning, several improvements were made to the cavity preparation

Fundamental SRF research and development





Figure 1: Nb_3Sn -coated cavity performance before and after the first Nb_3Sn -coated cavity pair assembly. Note the increase in the low-field surface resistance and strong field dependence in the pair test and the test after the pair assembly.

process, e.g., a special procedure and tooling was developed to shield the inner surface of cavities during chemical etching of niobium flanges in order to reduce the exposure of the coated inner surface to BCP vapor during treatment. Two new CEBAF 5-cell cavities of C75 shape [3] were procured from a commercial vendor, baselined in the vertical dewar tests, coated with Nb₃Sn film in Jefferson Lab Nb₃Sn coating system, and qualified for the pair assembly at Jefferson Lab.

With the adopted changes in the assembly process the coated cavity were assembled into the cavity pair and tested in the vertical dewar. The low-field surface resistance of the coated cavities was largely unchanged from the qualification tests: one cavity did not exhibit any degradation up to $E_{acc} = 3 \text{ MV/m}$, Fig. 2, and the low-field surface resistance in the other cavity increased by about $10 \text{ m}\Omega$. However, both cavities showed strong Q-slope above few MV/m of accelerating gradient, which limited field reach to below $E_{acc} = 10 \text{ MV/m}$ in both cavities.

The strong Q-slope degradation showed similarity in both cavities after the pair assembly. It was noticed that the resonant frequency of one of the cavities shifted by about 300 kHz from its value before the pair assembly. Although the other cavity showed little shift in the fundamental fre-

^{*} grigory@fnal.gov

21th Int. Conf. RF Supercond. ISBN: 978-3-95450-234-9

SRF2023, Grand Rapids, MI, USA JACoW Publishing doi:10.18429/JACoW-SRF2023-TUPTB010 ISSN: 2673-5504



Figure 2: Change in Nb₃Sn-coated cavity performance after the pair assembly with the new mitigation measures implemented. Note that the low-field surface resistance was preserved, but a strong Q-slope limits the gradient.

quency, we decided to re-evaluate all the assembly steps for mechanical stress again. Since these cavities are heat treated above 1100 °C during Nb₃Sn coating, they are softer than the typical niobium cavity and it was important to assess which steps may cause plastic deformation during cavity preparation and pair assembly.

This contribution discusses mechanical analysis to understand the potential causes of frequency shits, the mitigation measures, and the results of the Nb₃Sn-coated cavity performance in the cryogenic dewar testing after another pair assembly.

MECHANICAL SIMULATIONS

To better understand the cause for degradation and the frequency shifts after pair assemblies, mechanical simulations have been done to assess stresses on the cavities during different stages of string assembly. While we checked the stresses on the cavity in different configurations, including, for example, HPR fixtures, most focus was devoted to the handling of cavities during pair assemblies. In Fig. 3, the cavity pair on the support fixture called strongback is shown. The cavities are mounted onto the strongback after the final HPR. In this fixture each cavity is supported by two mechanical supports at each end. The supports allow the cavities to slide freely along the axial direction, but constrain their orthogonal motion. With mechanical simulation we looked at how support points affect the distribution of stresses in the cavity. As it can be expected for this configuration, the stresses were found to be well below plastic limits for niobium even after 1200 °C treatment [4] in this configuration.

While on the strongback, the two cavities are assembled with HOM and FPC waveguides and the end dish and joined together by the inner adapter. The cavities than form a hermetic pair that is pumped down and leak checked. The next critical step is the testing of the pair in cryogenic dewar at the vertical test facility. In order to install the pair into the



Figure 3: [top]Nb₃Sn-coated cavity pair assembled on the strongback. Each cavity is supported from the bottom at each end with three-point fixture. [bottom] Stress distribution in the cavity on the strongback in horizontal position. Note that the stresses are well below the plastic limit.

vertical dewar, the strongback with the pair is rotated vertical and the pair is transferred from the strongback to the vertical attachment on the vertical test stand, Fig. 4. The vertical attachment has recently been modified to constrain the pair better. The analysis of the cavity transfer and the cavity hanging in the vertical attachment on the test stand did not indicate any evidence for plastic limits to be exceeded under normal conditions. After the pair is mounted to the vertical attachment on the test stand, it is leak checked and is moved out of the cleanroom with the overhead crane to the cryogenic dewar. This cryogenic test of the cavity pair serves two purposes. One goal is to confirm that the pair was cleanly assembled and meets field emission specifications for the project. The other goal is to verify that the pair is hermetic and maintains its vacuum integrity in the superfluid liquid helium bath: the condition identical to what is seen by the pair inside the helium vessel during operation.

During the analysis of the mechanical simulation results, we realized that, while cavities are well supported and cavity handling with the manual lifts should not induce stresses in excess of niobium plastic limits, the crane movement of the pair is harder to constraint and control. Special damping fixtures need to be designed and tested to reduce the risk of mechanical deformation during this step. The design and testing of such fixtures were beyond the scope of this project, so, to mitigate the potential issue with crane moves, the decision was made to skip cryogenic dewar test of the cavity pair and proceed to the cryomodule assembly without a qualification test in the vertical dewar after the pair assembly.

CAVITY PERFORMANCE AFTER PAIR ASSEMBLY

For the next pair assembly, re-processing and re-coating with Nb₃Sn of two cavities was done. The decision was made to coat one cavity at Fermilab Nb3Sn coating facility

Fundamental SRF research and development

SRF2023, Grand Rapids, MI, USA JACoW Publishing ISSN: 2673-5504 doi:10.18429/JACoW-SRF2023-TUPTB010



Figure 4: [left] Nb₃Sn-coated cavity pair assembled on the vertical test stand in preparation for cryogenic testing in the vertical dewar. [center] CAD drawing of the modified vertical attachment support fixture [bottom] Stress distribution in the cavity on the vertical test stand. Note that the stresses are higher than in the horizontal position, but are still below the plastic limit.

and the other cavity at Jefferson Lab Nb₃Sn coating facility to expedite cavity re-qualification process. It was the first time that CEBAF 5-cell cavity was processed at Fermilab and coated with Nb₃Sn at Fermilab Nb₃Sn coating facility. During re-processing, the other cavity developed a leak in the weld joint of the fundamental power coupler waveguide. The reason for the leak was due to the thinning on one of the welds in the end groups of the cavity. While the cells in this C75 cavity were made out of niobium sheets purchased recently, the end groups were cut off the old cavities from the original CEBAF cavity production by Interatom, in order to save on the cost of cavity fabrication. One of these end groups, thinned by the recent and previous chemical treatments, developed a leak after latest chemical treatment. Attempts to fix the leak by electron beam welding proved unsuccessful. The cavity was thus unsuitable for additional coatings and had to be replaced with another niobium cavity. The new cavity was CEBAF C75 shape cavity, which, unlike other cavities discussed in this contribution, was made with large-grain niobium material. The efforts to re-coat this cavity progressed smoothly and the cavity was successfully coated with Nb₃Sn at Jefferson Lab Nb₃Sn coating facility. In Figs. 5 and 6, the vertical test results of qualification tests after the latest Nb₃Sn coatings of CEBAF 5-cell cavities from both facilities are shown. The vertical test performance of both cavities exceeded the gradient specification of 10 MV/m and met or exceeded the quality factor specification of 10^{10} at 4 K.

After the vertical cavity qualification tests, both cavities were prepared and assembled into the cavity pair. During pumpdown of the cavity pair after the pair assembly, a warm leak was discovered in the ceramic window of one of the fundamental power coupler waveguides. The pair had to be disassembled to replace the leaking waveguide. We disassembled the pair completely in order to test both cavities in the vertical dewar. The goal was to assess the impact of

Fundamental SRF research and development



Figure 5: Qualification test results of the cavity coated at Fermilab Nb₃Sn-coating facility. Note that the cavity gradient exceeds $E_{acc} = 14 \text{ MV/m}$ and Q_0 reaches 10^{10} at $E_{acc} = 10 \text{ MV/m}$ at 4.4 K, which is the goal. [inset] Pictures of the cavity assembled for the coating in the furnace, the picture of the inside surface of coated cavity, and the coating furnace layout reproduced from [5].



Figure 6: Qualification test results of the cavity coated at Jefferson Lab Nb₃Sn-coating facility. Note that the cavity gradient exceeds $E_{acc} = 13 \text{ MV/m}$ and Q_0 exceeds 10^{10} at $E_{acc} = 10 \text{ MV/m}$ at 4.4 K, which is the specification. [inset] the coating furnace layout reproduced from [6].

additional measures on preservation of the performance of Nb₃Sn-coated cavities.

Both cavities were completely disassembled, ultrasonically cleaned, high pressure water rinsed, assembled with vertical cavity test hardware in the cleanroom and tested in the vertical dewars at 4 K and 2 K. Low-field surface resistance of one cavity increased by about 10 m Ω to about 27 m Ω , and hence the quality factor of the cavity was still above 10¹⁰ at 4 K. The cavity exhibited Q-slope above E_{acc} =

TUPTB010

DO

and

publisher,

3 MV/m reaching $E_{acc} = 8$ MV/m with $Q_0 \approx 2 \times 10^{10}$, Fig. 7, which was higher than what were observed after the previous pair assembly attempt, Fig. 2.

The second cavity did not show any degradation in either quality factor or accelerating gradient after pair assembly, Fig. 8. Multipacting barrier was observed at around $E_{acc} = 15$ MV/m both at 4 K and 2 K. After multipacting barrier was processed in the vertical test at 2 K, the cavity reached $E_{acc} \approx 20$ MV/m, corresponding to 80 mT of the peak surface magnetic field, after the multipacting barrier was processed at around $E_{acc} = 15$ MV/m. This is the best performance and the highest accelerating gradient in Nb₃Sn-coated 5-cell cavities.



Figure 7: Nb_3Sn -coated cavity performance before and after the pair assembly with the new mitigation measures implemented. Note that the low-field surface resistance was preserved, but strong Q-slope limits the maximum accelerating gradient.

Since the total energy gain of two cavities was exceeding 10 MeV, which is one of the targets for this project, and one of the cavities preserved its quality factor of 10^{10} at $E_{acc} = 10 \text{ MV/m}$, we are progressing these cavities to the cavity pair assembly without any additional re-processing and re-coating. As of this writing the cavity pair has been assembled, passed the leak check, and is being integrated into the helium vessel (Fig. 9).

CONCLUSION

We investigated the degradation of Nb_3Sn -coated cavities after preparation and assembly into the cavity pair. CEBAF cavity pair is the milestone for integrating cavities into CEBAF cryomodule. In the previous attempts, significant reductions in quality factors and maximum accelerating gradients have been observed after pair assemblies. Several causes, such as mechanical tuning at room temperature, were identified and mitigated to maintain the quality factor and gradient reach from the vertical dewar qualification test through pair assemblies. As an additional precaution, vertical dewar test of the cavity pair after its assembly, which is

ТИРТВО10



Figure 8: Nb₃Sn-coated cavity performance before and after the pair assembly with the new mitigation measures implemented. No change in the cavity performance was observed. After the pair assembly, the cavity reached close to 20 MV/m accelerating gradient, which corresponds to about 80 mT of the peak surface magnetic field.

Eacc [MV/m]



Figure 9: Nb_3Sn cavity pair prepared for helium vessel integration. The original CEBAF cavities did not have local magnetic shielding only global magnetic shielding. This pair, similar to other C75 pair, employs both local and global magnetic shielding [7].

the standard step in CEBAF cryomodule assembly, was eliminated from the preparation process. As the result of these measures, one cavity exhibited some degradation, while the other cavity fully maintained its performance after the pair assembly. The best cavity reached close to 20 MV/m accelerating gradient, which corresponds to about 80 mT of the peak surface magnetic field. Since the total energy gain of the pair exceeds 10 MeV, the cavities are progressing to cryomodule assembly without re-processing and re-coating.

ACKNOWLEDGMENTS

This manuscript has been authored by Fermi Research Alliance, LLC under Contract No. DE-AC02-07CH11359 with the U.S. Department of Energy, Office of Science, Office of High Energy Physics. This material is based upon work supported by the U.S. Department of Energy, Office of Science, Office of Nuclear Physics.

Fundamental SRF research and development

REFERENCES

 G. Eremeev *et al.*, "RF Performance Sensitivity to Tuning of Nb₃Sn Coated CEBAF Cavities", in *Proc. 19th Int. Conf. RF Supercond. (SRF'19)*, Dresden, Germany, Jun.-Jul. 2019, pp. 55–59.

doi:10.18429/JACoW-SRF2019-MOP015

- [2] S. Posen *et al.*, "Nb₃Sn at Fermilab: Exploring Performance", in *Proc. 19th Int. Conf. RF Supercond. (SRF'19)*, Dresden, Germany, Jun.-Jul. 2019, pp. 818–822. doi:10.18429/JACoW-SRF2019-THFUB1
- [3] R. Rimmer *et al.*, "Upgraded Cavities for the CEBAF Cryomodule Rework Program", in *Proc. 18th Int. Conf. RF Supercond.* (*SRF'17*), Lanzhou, China, Jul. 2017, pp. 168–172. doi:10.18429/JAC0W-SRF2017-MOPB049

- [4] T. E. Tietz and J. W. Wilson, *Behavior and Properties of Refractory Metals*, Stanford University Press, Stanford, CA, USA, 1965.
- [5] S. Posen and D. L. Hall, "Nb₃Sn superconducting radiofrequency cavities: fabrication, results, properties, and prospects", *Supercond. Sci. Technol.*, vol. 30, p. 033004, 2017. doi:10.1088/1361-6668/30/3/033004
- [6] G. Eremeev et al., "Nb₃Sn multicell cavity coating system at Jefferson Lab", *Rev. Sci. Instrum.*, vol. 91, p. 073911, 2020. doi:10.1063/1.5144490
- [7] M. Drury *et al.*, "Commissioning of the Prototype C75 Cavities in a CEBAF Cryomodule", *Proc. 9th Int. Part. Accel. Conf. (IPAC'18)*, Vancouver, Canada, Apr.-May 2018, pp. 3961–3964. doi:10.18429/JACoW-IPAC2018-THPAL134